



1/72

REPLACEMENT SHEET




FIG. 1
(PRIOR ART)




FIG. 2




FIG. 3

4/72




FIG. 4A

5/72

REPLACEMENT SHEET




FIG. 4B





FIG. 5

7/72

REPLACEMENT SHEET

FIG. 6A



8/72

REPLACEMENT SHEET




FIG. 6B

9/72

REPLACEMENT SHEET




FIG. 6C

10/72

REPLACEMENT SHEET




FIG. 6D

11/72

REPLACEMENT SHEET




FIG. 6E

12/72

REPLACEMENT SHEET




FIG. 7A

13/72




FIG. 7B

14/72




FIG. 8

15/72




FIG. 9A




FIG. 9B

17/72

REPLACEMENT SHEET




FIG. 10A





FIG. 10B

FIG. 11A



20/72





FIG. 11B

21/72

FIG. 11C



22/72

FIG. 12A





FIG. 12B



24/72

REPLACEMENT SHEET




FIG. 13A





FIG. 13B

26/72







FIG. 14B

28/72

FIG. 15A



29/72

FIG. 15B




FIG. 16A





FIG. 16B



32/72

REPLACEMENT SHEET




FIG. 17A

33/72




FIG. 17B

34/72




FIG. 18A

35/72

	TS1	TS2	TS3
HANDSET A			
Transmit	C	ATBR	ATCR
Receive	C	CTAR	BTAR
HANDSET B			
Transmit	C	BTAR	BTAR
Receive	C	ATBR	CTBR
HANDSET C			
Transmit	C	CTAR	CTBR
Receive	C	BTAR	ATCR

FIG. 18B

	TS1	TS2	TS3
HANDSET A			
Transmit	C	ATBR	ATCR
Receive	CTAR	BTAR	C
HANDSET B			
Transmit	BTCR	BTAR	C
Receive	C	ATBR	CTBR
HANDSET C			
Transmit	CTAR	C	CTBR
Receive	BTCR	C	ATCR

FIG. 18C




FIG. 19A




FIG. 19B




FIG. 20A




FIG. 20B

40/72

FIG. 21A






FIG. 21B



41/72

FIG. 22A



42/72




FIG. 22B

43/72




FIG. 23A

44/72

REPLACEMENT SHEET





FIG. 23B

45/72

FIG. 24A



46/72

REPLACEMENT SHEET




FIG. 24B

47/72




FIG. 25A

48/72

REPLACEMENT SHEET





FIG. 25B

49/72

FIG. 26A



50/72




FIG. 26B

51/72




FIG. 27A

52/72




FIG. 27B

53/72




FIG. 27C

54/72




FIG. 28

55/72





FIG. 29

56/72

FIG. 30A



57/72




FIG. 30B

58/72




FIG.31A

59/72





FIG. 31B

60/72



61/72




FIG. 33

62/72




FIG. 34

63/72

2000




FIG. 35

64/72

3000





FIG. 36

65/72

FIG. 37






FIG. 38

67/72




FIG. 39A

68/72




FIG. 39B

69/72




FIG. 40A

70/72




FIG. 40B

71/72




FIG. 41A

72/72




FIG. 41B